

ASBESTOS ASSESSMENT SURVEY

H-K Building #: 37
 Project Number: 0980193E
 Project: G. HEILEMAN BREWERY "E"
 Date Inspected: 03/27/89
 Inspector: CURT BAXTER

Building Number: 37
 Building Name: PARTS
 SEATTLE, WASHINGTON 98134
 Building Type: GARAGE
 Year Constructed: 1949

| | | | | |
|-------|-----------------|-------------------------------------|-----------------------------|-------|
| ***** | AREA NUMBER: 01 | AREA DESCRIPTION: 1st Floor-Ceiling | AREA AVERAGE % ASBESTOS: 0% | ***** |
|-------|-----------------|-------------------------------------|-----------------------------|-------|

| LOCATION OF THE MATERIAL | SAMPLE NUMBER | ASB | MATERIAL DESCRIPTION | O&M CODE | QUANTITY | UNITS OF MEASURE | PIPE ID | EXP POT | PL | REMOVAL COSTS | REPLACEMENT COSTS | TOTAL COSTS |
|--------------------------|------------------|-----|----------------------|-------------|------------|---------------------|------------|------------|----|------------------|----------------------|----------------|
| throughout | 02-356624 | 0% | acoustical tile | OMG | 280 sq.ft. | | | | | | | |
| | 02-356625 | 0% | | | | | | | | | | |
| | 02-356626 | 0% | | | | | | | | | | |

| | | | | |
|---------------|-----------------|-----|-----|-----|
| AREA COMMENTS | AREA # 01 TOTAL | \$0 | \$0 | \$0 |
|---------------|-----------------|-----|-----|-----|

| | | | | |
|-------|-----------------|-----------------------------|-----------------------------|-------|
| ***** | AREA NUMBER: 02 | AREA DESCRIPTION: 1st Floor | AREA AVERAGE % ASBESTOS: 9% | ***** |
|-------|-----------------|-----------------------------|-----------------------------|-------|

| LOCATION OF THE MATERIAL | SAMPLE NUMBER | ASB | MATERIAL DESCRIPTION | O&M CODE | QUANTITY | UNITS OF MEASURE | PIPE ID | EXP POT | PL | REMOVAL COSTS | REPLACEMENT COSTS | TOTAL COSTS |
|--------------------------------------|------------------|-----|-------------------------------|-------------|----------|---------------------|------------|------------|-----|------------------|----------------------|----------------|
| center of room-between storage racks | 01-356621 | 10% | mjp on non-suspect pipe cover | OMA | 1 | 6 in. O.D. | DR | 25 | 111 | \$39 | \$23 | \$62 |
| | 01-356622 | 10% | | | | | | 25 | 111 | | | |
| | 01-356623 | 8% | | | | | | 25 | 111 | | | |

| | | | | |
|---------------|-----------------|------|------|------|
| AREA COMMENTS | AREA # 02 TOTAL | \$39 | \$23 | \$62 |
|---------------|-----------------|------|------|------|

The material is in good condition with minor contact and water damage. The material is approximately 8' from the floor. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

| | | | |
|---------------------|------|------|------|
| BUILDING # 37 TOTAL | \$39 | \$23 | \$62 |
|---------------------|------|------|------|